

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 2070/PWD Dt. 23-01-1970)


- Name of the Officer: Jayakumar, G.
 - Name of the School: St. Mary's Bethany Central School, Valakom
 - Location with name of Education District/ Sub. District: Valakom, Kottarakkuda
 - Classification of Building as specified in column 4 of the application for fitness certificate and size:
 - 27.25m x 10.20m x 3.05m
 - 173.11m² x 3.90m Basement floor
 - 621.46m² x 3.90m ground floor
 - 621.46m² x 3.90m first floor
 - Period for which the certificate is issued: 2022-2023
 - Nature of defects, if any:
 - Foundation and basement
 - Superstructure
 - Doors and Windows
 - Wood work wrought and put up: Nil
 - Roof
 - Flooring
 - Miscellaneous (Cracks, etc.)
 - Any major defects noticed which will render the building unsafe in any manner
 - Whether maintenance works have been done properly: Yes
 - Whether the structure is sound or not for conducting classes: The structure is sound to conduct the classes under normal weather conditions
- Note: 1. The stability of the structure should be examined also with reference to location, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

certified that the school building was inspected by me on 13.05.2022 and found to be fit / unfit to conduct classes, for the period 2022-2023 for the reasons stated above.

Place: Ummammad
Date: 16.05.2022

The Principal
St. Mary's Bethany Central School
Valakom



The Manager
Assistant Engineer
St. Mary's Bethany Central School
Valakom